Environmental Health and Safety 2220 Circle Drive Cleveland, Ohio 44106 P: (216) 368-2906

F: (216) 368-2236 cwruehs@case.edu

Cesium (Cs-134)

Half Life: 2.1 years

Radiation: Beta, Gamma and X-

Special Precautions:

Store Cs-134 behind adequate lead (Pb) shielding (minimum $\frac{1}{4}$ inch lead)

Use tools to indirectly handle unshielded sources and potentially contaminated containers - no direct hand contact Ensure that an appropriate, operational survey meter is present in the work area and turned on whenever Cs-134 is handled to immediately detect contamination